

Photo #	Description	Date	Time	Direction	Taken By
GEDC1079	Spill location before remediation from within the wall	1/7/2011	0932	Down	MAB
GEDC1081	Trim removed, mercury beads observed	1/7/2011	0938	Down	MAB
GEDC1082	Closeup of mercury beads located within the wall, near the spill location	1/7/2011	0938	Down	MAB
GEDC1084	Closeup of mercury beads located within the wall, near the spill location	1/7/2011	0939	Down	MAB
GEDC1085	Closeup of mercury beads located within the wall, near the spill location	1/7/2011	0939	Down	MAB
GEDC1086	Preparing to remove mercury with merc-vac and seal wall	1/7/2011	0939	Down	MAB
GEDC1087	Silicon seal installed behind trim, at corner of floor and wall	1/7/2011	1011	Down	MAB
GEDC1088	Silicon seal installed behind trim, at corner of floor and wall	1/7/2011	1011	Down	MAB
GEDC1089	First coat of Kilz2 primer/sealer to spill area and heat vent	1/7/2011	1055	Down	MAB
GEDC1090	Familyroom after cleanup of mercury contamination and final screening	1/7/2011	1901	NW	MAB
GEDC1091	Familyroom after cleanup of mercury contamination and final screening	1/7/2011	1901	NW	MAB
GEDC1092	Familyroom after cleanup of mercury contamination and final screening	1/7/2011	1901	W	MAB
GEDC1093	Familyroom after cleanup of mercury contamination and final screening	1/7/2011	1902	NW	MAB
GEDC1094	Kitchen after cleanup of mercury contamination and final screening	1/7/2011	1902	NE	MAB
GEDC1095	Installation of padding over carpet tack-strip, near front door	1/7/2011	1902	Down	MAB



